

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401840237
Date Received:
11/14/2018

FIR RESOLUTION FORM

CA Summary:
4 of 4 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Baca, Matt		matthew.baca@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603182
Inspection Date: 10/05/2018 FIR Submit Date: 10/22/2018 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333123

Location Name: KNIGHT GAS UNIT-N32N7W Number: 17SWNE County: LA PLATA
Qtrqtr: SWNE Sec: 17 Twp: 32N Range: 7W Meridian: N
Latitude: 37.020556 Longitude: -107.628525

FACILITY - API Number: 05-067-00 Facility ID: 216236

Facility Name: KNIGHT B Number: 1
Qtrqtr: SWNE Sec: 17 Twp: 32N Range: 7W Meridian: N
Latitude: 37.020556 Longitude: -107.628525

CORRECTIVE ACTIONS:

1 CA# 119777

Corrective Action: Remove cable debris. Date: 11/16/2018

Response: CA COMPLETED Date of Completion: 11/07/2018

Operator Comment: Actions Complete

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 119778

Corrective Action: Mark or remove guy line anchors.

Date: 11/16/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator
Comment: Actions Complete

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 119780

Corrective Action: Install erosion controls to stabilize erosion within the southern portion of the project area and within the southeastern diversion at the access entrance. Successful revegetation will significantly improve stabilization.

Date: 11/23/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator
Comment: Actions Complete

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 CA# 119810

Corrective Action: Revegetate southern cut and fill slopes within the fall or spring seeding windows. Mulching is recommended for successful seedling establishment and soil protection.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator
Comment: Actions Complete

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Actions Complete

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matthew Baca

Signed: _____

Title: Construction Specialist

Date: 11/14/2018 5:11:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401840237	FIR RESOLUTION SUBMITTED
401840240	Corrective Pics

Total Attach: 2 Files