

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401877680
Date Received:
12/17/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name: _____
Phone: () Fax: ()
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Baca, Matt		matthew.baca@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603127
Inspection Date: 09/25/2018 FIR Submit Date: 10/01/2018 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306861

Location Name: FEINBERG GAS UNIT C- Number: 28NWSW County: LA PLATA
N35N6W
Qtrqtr: NWS Sec: 28 Twp: 35N Range: 6W Meridian: N
Latitude: 37.270211 Longitude: -107.538160

FACILITY - API Number: 05-067- -00 Facility ID: 270213

Facility Name: FEINBERG C Number: 2
Qtrqtr: NWS Sec: 28 Twp: 35N Range: 6W Meridian: N
Latitude: 37.270211 Longitude: -107.538160

CORRECTIVE ACTIONS:

1 ☒ CA# 119139

Corrective Action: Revegetation is needed on portions of the cut and fill slopes with little to no vegetation. Seeding is required by November 15, 2018 and should be done in conjunction with stormwater activities described below. Mulching is recommended.

Date: 11/15/2018

Response: CA COMPLETED Date of Completion: 11/15/2018

Action Completed

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 119140

Corrective Action: Erosion controls are needed on the well pad cut and fill slopes. Measures such as slope run-on controls, erosion blanket on cut slopes until vegetation can be established, additional seeding, and cattle exclusion is likely needed. Stormwater controls are also needed in the erosional channel in the northeastern project area to de-energize flows and stabilize the banks.

Date: 11/15/2018

Response: CA COMPLETED

Date of Completion: 11/15/2018

Operator
Comment:

Action Completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Actions Completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matthew Baca

Signed: _____

Title: Construction Specialist

Date: 12/17/2018 3:47:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401877680	FIR RESOLUTION SUBMITTED
401877685	Corrective Pics

Total Attach: 2 Files