

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401597789  
Date Received:  
04/05/2018

FIR RESOLUTION FORM

CA Summary:  
1 of 1 CAs from the FIR responded to on this Form  
1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330  
Name of Operator: SG INTERESTS I LTD  
Address: 100 WAUGH DR SUITE 400  
City: HOUSTON State: TX Zip: 77007  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Hughes, Jim		jimo.hughes@state.co.us
Roy, Catherine		catherine.roy@state.co.us
Arthur, Denise		denise.arthur@state.co.us
fischer, ales		alex.fischer@state.co.us
.		inspection@sginterests.com
Conklin, Curtis		curtis.conklin@state.co.us
Labowskie, Steve		steve.labowskie@state.co.us
Kellerby, Shaun		shaun.kellerby@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602285  
Inspection Date: 12/05/2017 FIR Submit Date: 12/11/2017 FIR Status:

Inspected Operator Information:

Company Name: SG INTERESTS I LTD Company Number: 77330  
Address: 100 WAUGH DR SUITE 400  
City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 428197

Location Name: Eck 12-90-1 Number: 428197 County: GUNNISON  
Qtrqr: LOT 1 Sec: 1 Twp: 12S Range: 90W Meridian: 6  
Latitude: 39.048120 Longitude: -107.390430

FACILITY - API Number: 05-051-00 Facility ID: 428196

Facility Name: ECK 12-90-1 Number: 1  
Qtrqr: LOT 1 Sec: 1 Twp: 12S Range: 90W Meridian: 6  
Latitude: 39.048120 Longitude: -107.390430

CORRECTIVE ACTIONS:

Corrective Action: Corrective action to install stabilization measures on well pad cut-slopes by November 30, 2017 is not addressed. Sediment piles on slopes along the access road and above culverts need to be removed and properly disposed of. If vegetation is damaged, then re-seeding is required. Corrective action date will remain to document time since original corrective action date.

Date: 11/30/2017

Response: CA COMPLETED

Date of Completion: 12/15/2017

Operator Comment: Attached photos show installation of a diversion ditch above the cut slope to mitigate run-on onto the slope. Additional photos show deepening of the on-pad diversion ditch in preparation for installation of Jute matting in the spring of 2018. Also, the sediment piles from cleaning out culverts have been removed and seeding occurred where necessary.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: In November and December 2017, SG addressed the cut-slope erosion concerns identified on the 680602118 and 680602285 inspection forms. Another inspection from 4/4/2018 (688800037) identified that the "cut slope did not appear to be stabilized as required by inspection document 680602118." SG discussed plans to address these concerns with COGCC and was granted a short-term installation requirement due by 11/30/2017 and a long term installation requirement due by 5/20/2018. SG installed a diversion ditch above the cut-slope to address the short term requirement and will install Jute matting by May 30, 2018 to address the long term requirement. Attached are photos of the diversion ditch installed and completed in December 2017.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Blanchard

Signed: \_\_\_\_\_

Title: Env & Reg Manager

Date: 4/5/2018 9:24:16 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
401597789	FIR RESOLUTION SUBMITTED
401597804	Eck cutslope addressed

Total Attach: 2 Files