

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2018

Submitted Date:

12/21/2018

Document Number:

680304351**FIELD INSPECTION FORM**

Loc ID 312301 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chisholm, James Jr.		investmentequipment@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221138	WELL	PR	04/06/2016	OW	075-09264	COLORADO 1-10	PR

General Comment:

Routine Site Inspection -

NOTE TO OPERATOR: Read all CA's - Perform CA's - Submit Form 42 to COGCC for re-inspection scheduling.

Location

Lease Road:			
Type	Access		
comment:	Satisfactory		
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Placarding on PW tanks is inadequate		
Corrective Action:	Install placarding/signage on PW tanks with contents/quantities/fire code. Comply with Rule 210 series	Date:	02/20/2019
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	No change in equipment inventoried.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		Open Top		,
Comment:	Skim tank @ PW pit shows crude in tank. Common practice by Operator's has been to remove open top skim tank with partially buried fiberglass tank with top hatch. Recommended compliance remedy.				
Corrective Action:	Remove fluids or remove tank - repair netting on tank, verify that existing tank has impermeable bottom. Comply with Rules 323, 324 A.a,907.c				Date: 01/01/2019

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No					
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	221138	Type:	WELL	API Number:	075-09264	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	OW								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401884252	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685540
680304352	Skim tank crude - netting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685522
680304353	PW tank labeling-placarding	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685523
680304354	PW tank labeling-placarding	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685524
680304355	Sign @ Crude tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4685525