

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2019

Submitted Date:

01/16/2019

Document Number:

688401044**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 308317      Silver, Randy      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER      State: CO      Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	<a href="#">All Inspections</a>
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266154	WELL	PR	03/01/2018	GW	071-07817	HILL RANCH 34-08	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location sign		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Packing on WH leaking at time of inspection		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	01/17/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment , polis rod pipe and door of sep house		
Corrective Action:	Comply with Rule 603.f .	Date:	02/16/2019
Type	OTHER		
Comment:	Stained soil around motor skid		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	02/16/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 266154 Type: WELL API Number: 071-07817 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Comment: Apears not to be plumbed to surface at time of inspection

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<u>Packing was leaking at time of inspection. Contacted Timber Creek rep he said he would send someone to repair.</u>	silverr	01/16/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401045	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706162">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706162</a>