

Location

Overall Good:

Signs/Marker:

Type	OTHER			
Comment:	LOCATION SIGN			
Corrective Action:			Date:	

Emergency Contact Number:

Comment:			Date:	
Corrective Action:			Date:	

Good Housekeeping:

Type	OTHER			
Comment:	STAINED SOIL UNDER APPARENT HYDRAULIC HOSE LEAK. STAINED SOIL NEAR COMPRESSOR SKID. SEE LOC PICS			
Corrective Action:	Properly treat or dispose of stained soil in accordance with Rule 907.e		Date:	02/16/2019
Type	OTHER			
Comment:	HYDRAULIC HOSE APPEARS TO BE LEAKING AT THREADED CONNECTION. SEE LOC PICS.			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	02/16/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

				corrective date
Type: Compressor	# 1			
Comment:	WELL APPEARS TO BE PRODUCED BY VACUUM AND HAS NO SUNDRY ON RECORD.			
Corrective Action:	COMPLY WITH RULE 331.		Date:	02/16/2019

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Inspected FacilitiesFacility ID: 259238 Type: WELL API Number: 071-07211 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
	beardslt	01/16/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401908044	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706224
695100021	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706204