

## Inspection Photos

Location Name: My Way Ranch 17-7 Pad

Location ID: #334518 Spill/Release ID: #460723

Inspection Date: January 15, 2019



Photo #1 – Facility sign.



Photo #2 – View of NW tank battery from south side. Red arrow points to location of 1/4" stainless steel line inside of tank battery SPCC.

## Inspection Photos

Location Name: My Way Ranch 17-7 Pad

Location ID: #334518 Spill/Release ID: #460723

Inspection Date: January 15, 2019



**Photo #3 – View of SW tank battery from north.  
Spill/Release ID #460723 occurred on the south side of this  
tank battery.**



**Photo #4 – View of filter socks and stained snow inside of  
SW tank battery truck loadout SPCC. Refer to R. Murray's  
inspection (doc #693200212) for corrective action.**



## Inspection Photos

Location Name: My Way Ranch 17-7 Pad

Location ID: #334518 Spill/Release ID: #460723

Inspection Date: January 15, 2019



**Photo #5 – Free product inside of SW tank battery truck loadout SPCC. Refer to R. Murray’s inspection (doc #693200212) for corrective action.**



**Photo #6 – View of tank leveling pipe that was the source of fluids released by Spill/Release ID #460723 from south side of tank battery.**

## Inspection Photos

Location Name: My Way Ranch 17-7 Pad

Location ID: #334518 Spill/Release ID: #460723

Inspection Date: January 15, 2019



**Photo #7 – View of areas inside and outside of tank battery SPCC from east side. Operator indicated that fluids released during Spill/Release ID #460723 had impacted soil outside of SPCC.**



**Photo #8 – Additional used filter socks stored on location. Refer to R. Murray's inspection (doc #693200212) for corrective action.**

