

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401924224

Date Received:

01/30/2019

## FIR RESOLUTION FORM

### CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10670

Name of Operator: MALLARD EXPLORATION LLC

Address: 1400 16TH STREET SUITE 300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Erin Mathews

720-543-7959

emathews@mallardexploration.com

Dustin Dyk

720-543-7954

ddyk@mallardexploration.com

cogccinspections@mallardexploration.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682504449

Inspection Date: 01/25/2019

FIR Submit Date: 01/25/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: MALLARD EXPLORATION LLC

Company Number: 10670

Address: 1400 16TH STREET SUITE 300

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 453517

Location Name: Green Teal Number: Pad County: \_\_\_\_\_

Qtrqr: SESW Sec: 34 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.612876 Longitude: -104.081402

### FACILITY - API Number: 05-123-00 Facility ID: 453517

Facility Name: Green Teal Number: Pad

Qtrqr: SESW Sec: 34 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.612876 Longitude: -104.081402

### CORRECTIVE ACTIONS:

1 ☒ CA# 122041

Corrective Action: Install required stormwater and erosion control BMPs in accordance with Rule 1002.f and good engineering practices.

Date: 02/01/2019

Response: CA COMPLETED

Date of Completion: 01/30/2019

Operator Comment: Perimeter stormwater controls consisting of a ditch and/or ditch and berm have been constructed around the perimeter of the pad. Construction of the BMP is complete and material has been compacted. Straw wattles were installed on the top edge of the pad along the southern edge. Refer to attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 122042

Corrective Action: Install required stormwater and erosion control BMPs in accordance with Rule 1002.f and stabilize soil stockpiles in accordance with 1002.c

Date: 02/01/2019

Response: CA COMPLETED

Date of Completion: 01/30/2019

Operator Comment: The topsoil stockpile has been tracked. A ditch and/or ditch and berm has been constructed around the topsoil pile to serve as a perimeter BMP. Refer to attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

3 ☒ CA# 122043

Corrective Action: Install required stormwater and erosion control BMPs in accordance with Rule 1002.f and good engineering practices.

Date: 02/01/2019

Response: CA COMPLETED

Date of Completion: 01/30/2019

Operator Comment: Perimeter stormwater controls consisting of a ditch and/or ditch and berm have been constructed around the perimeter of the pad. Construction of the BMP is complete and material has been compacted. Refer to attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

4 ☒ CA# 122124

Corrective Action: Comply with rule 1002.e and 1002.f, and immediately install required stormwater and erosion control BMPs to stabilize the location and mitigate wind erosion and sediment transport.

Date: 01/29/2019

Response: CA COMPLETED

Date of Completion: 01/29/2019

Operator Comment: To mitigate the potential for wind erosion water was applied to the pad on 1/29/2019. Additionally pad construction is now complete and the entire pad has been compacted and additional base coarse material has been applied to around the wellheads in high traffic areas.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Per email correspondence with reclamation specialist, a COGCC server issue prevented operators from receiving inspection reports in a timely manner. The CA date for Wind erosion was changed from 1/25/2019 to 1/29/2019. Mallard received notice of the inspection on 1/29/2019.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Erin Mathews

Signed: \_\_\_\_\_

Title: VP Development

Date: 1/30/2019 10:51:34 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401924224	FIR RESOLUTION SUBMITTED
401924225	Location Photos

Total Attach: 2 Files