

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/04/2019

Submitted Date:

02/11/2019

Document Number:

679400287**FIELD INSPECTION FORM**
 Loc ID 319937 Inspector Name: CHESSON, BOB On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 12400Name of Operator: BYRON OIL INDUSTRIES INCAddress: 154 CLARKSON EXECUTIVE PARKCity: BALLWIN State: MO Zip: 63011**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
BYRON, RICHARD	636-391-8770	byronoil@aol.com	ALL INSPECTIONS
Gomez, Jason		jason.gomez@state.co.us	

General Comment:

Inspection for production pit closure (remediation #12152). Pit unclaimed. Stockpiled soils material on lease. Stockpiled soils must be removed to appropriate disposal by 3/8/19.

Stormwater erosion on southern edge of PW pit. Stormwater erosion controls must be repaired and/or enhanced by 3/8/19.

Production pit will remain as "active" status until reclaimed. Operator will file sundry notice to EPS when pit has been reclaimed.

See photos.

Location Construction

Location ID: 319937 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: Stormwater erosion on southern end of PW pit.

Corrective Action: Beef-up stormwater controls on southern end of PW pit.

Date: 03/08/2019

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spill/Remediation:**Comment: [Stockpiled soils need removal to appropriate disposal site.](#)Corrective Action: [Remove stockpiled soils to disposal site. Provide COGCC with disposal tickets,](#)

Date: 03/08/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Inspection for production pit closure (remediation #12152). Pit unclaimed. Stockpiled soils material on lease. Stockpiled soils must be removed to appropriate disposal by 3/8/19. Stormwater erosion on southern edge of PW pit. Stormwater erosion controls must be repaired and/or enhanced by 3/8/19. Production pit will remain as "active" status until reclaimed. Operator will file sundry notice to EPS when pit has been reclaimed. See photos.	chessonr	02/06/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679400288	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4730586