

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2019

Submitted Date:

02/13/2019

Document Number:

680304603

FIELD INSPECTION FORM

Loc ID 313839 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
225931	WELL	PR	08/01/2018	OW	087-06392	STROMSOE 1	PR

General Comment:

P&A in process. Extreme freezing temperatures required postponement of P&A.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 225931 Type: WELL API Number: 087-06392 Status: PR Insp. Status: PR

Cement

Cement Contractor

Contractor Name: Yetter Well Service

Contractor Phone: 970-522-2885

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Extreme cold temperature caused P&A in process to be postponed. BOP frozen.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Extreme cold temperatures caused delay in P&A process. BOP frozen.	schureky	02/13/2019