

HILL RANCH 34-08 API# 05-071-07817- TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 18, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401044



PHOTO 1: THE PACKINGS WERE RELACED, ELIMINATING THE WATER LEAK.

HILL RANCH 34-08 API# 05-071-07817– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: FEBRUARY 11, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401044



PHOTO 2: THE UNUSED EQUIPMENT WAS REMOVED FROM THE LOCATION.

HILL RANCH 34-08 API# 05-071-07817– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: FEBRUARY 11, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401044



PHOTO 3: THE BROKEN DOOR WAS REMOVED FROM THE LOCATION.

HILL RANCH 34-08 API# 05-071-07817- TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: FEBRUARY 11, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401044



PHOTO 4: THE STAINS ON THE GROUND WERE REMOVED.