

GOLDEN EAGLE 33-03 API # 05-071-09508 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401107



PHOTO 1: THE OIL ACCUMULATION ON THE LIQUID RING WAS REMOVED AND THE SKID WAS CLEANED. THE STAINS ON THE GROUND WERE REMOVED AND THE TRASH ON THE SKID WAS DISPOSED OF.

GOLDEN EAGLE 33-03 API # 05-071-09508 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401107



PHOTO 2: THE FLUID ACCUMULATION THAT WAS ON THE LIQUID RING SKID AND RESERVOIR WAS REMOVED AND THE SKID WAS CLEANED.

GOLDEN EAGLE 33-03 API # 05-071-09508 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401107



PHOTO 3: THE ELECTRIC FENCE WAS REPAIRED.

GOLDEN EAGLE 33-03 API # 05-071-09508 - TIMBER CREEK
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401107



PHOTO 4: THE RISER WAS LABELED.