

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401945322

Date Received:

02/20/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 51065

Name of Operator: LOEB LLC* HERMAN L

Address: P O BOX 838

City: LAWRENCEVILLE State: IL Zip: 62439

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Middagh, Jesse

815-556-0756

jesse@loeboil.com

Pelton, Shane

620-617-5870

shane@loeboil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682600608

Inspection Date: 01/31/2019

FIR Submit Date: 02/01/2019

FIR Status: _____

Inspected Operator Information:

Company Name: LOEB LLC* HERMAN L

Company Number: 51065

Address: P O BOX 838

City: LAWRENCEVILLE State: IL Zip: 62439

LOCATION - Location ID: 321694

Location Name: WHITE AL-614S42W Number: 24NESE County: CHEYENNE

Qtrqr: NESE Sec: 24 Twp: 14S Range: 42W Meridian: 6

Latitude: 38.818954 Longitude: -102.055057

FACILITY - API Number: 05-017-00 Facility ID: 207803

Facility Name: WHITE AL Number: 2

Qtrqr: NESE Sec: 24 Twp: 14S Range: 42W Meridian: 6

Latitude: 38.818954 Longitude: -102.055057

CORRECTIVE ACTIONS:

1 CA# 122237

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 03/02/2019

Response: CA COMPLETED

Date of Completion: 02/19/2019

Operator
Comment:

Partially completed. Plan is in place pending adequate weather and ground conditions to fully complete job.
Hard cake buildup around well head cannot be safely and properly removed until ground conditions improve.
Plan is to digout wellhead during upcoming spring season and replace with fresh soil / sand. Seeking extension of deadline to execute final stage of field corrective actions.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 122238

Corrective Action: Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.

Date: 02/02/2019

Response: CA COMPLETED

Date of Completion: 02/02/2019

Operator Comment: Casing vent was removed from wellhead. Valve closed and plug installed. Photo attached. Operator is taking necessary steps including data collection to seek request for venting from COGCC in near future.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 122239

Corrective Action: Install sign to comply with Rule 210.b.

Date: 03/02/2019

Response: CA COMPLETED

Date of Completion: 02/04/2019

Operator Comment: Updated contact information on signage. Photo attached.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action implemented. Hard cake around well head will be fully dug out in spring and replaced with fresh soil / sand.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jesse Middagh

Signed: _____

Title: Manager; E&P Ops

Date: 2/20/2019 10:56:53 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401945348	Contact information updated on well signage
401945351	Valve closed and plug installed on casing vent

Total Attach: 2 Files