

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401730806
Date Received:
08/10/2018

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Ray, Mandy	(505) 324-5122	mray@hilcorp.com
Shorty, Priscilla		pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602807
Inspection Date: 07/09/2018 FIR Submit Date: 07/09/2018 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306942

Location Name: OLGUIN-N32N7W Number: 13NESE County: LA PLATA
Qtrqtr: NESE Sec: 13 Twp: 32N Range: 7W Meridian: N
Latitude: 37.014190 Longitude: -107.555110

FACILITY - API Number: 05-067-00 Facility ID: 280796

Facility Name: OLGUIN Number: 100S
Qtrqtr: NESE Sec: 13 Twp: 32N Range: 7W Meridian: N
Latitude: 37.014190 Longitude: -107.555110

CORRECTIVE ACTIONS:

1 CA# 117362

Corrective Action: Project area needs to be properly decompacted and recontoured, and revegetated. Pit area in southern project area needs to be closed and debris properly disposed of. Weeds need to be controlled. This work needs to be completed during the fall 2018 seeding window, and no later than November 1, 2018. Date: 11/01/2018

Response: CA COMPLETED Date of Completion: 08/09/2018

Operator Comment: Fee Surface Owner has requested that the land be recontoured to his specs, the debris that is on location is the surface owners.

COGCC Decision: **Not Approved**

COGCC Representative: This location remains out of compliance if corrective actions are not addressed, enforcement actions may be pursued. Request below would require a comprehensive variance request in accordance with COGCC rules and guidance. Request would have to demonstrate that it would be protective of public health, safety, and welfare including the environment, and that long term stabilization can be achieved.

2  CA# 117363

Corrective Action: Stormwater controls are needed in the short term (August 9, 2018), to stabilize erosional channels in the southern and southwestern project area. Recontouring needs to repair the cut-slope scar, and long term stabilization will be met via successful vegetation establishment. A significantly reduced slope angle will be necessary to achieve vegetation establishment on the slope. Stormwater controls and monitoring are needed to ensure stabilization until the location passes final reclamation.

Date: 08/09/2018

Response: CA COMPLETED

Date of Completion: 08/09/2018

Operator Comment: Fee Surface owner has requested the erosional channels be set up to his specifications, our Construction person is attempting to reach out to the Landowner to let them know we need to bring the location up to the Specifications of the COGCC.

COGCC Decision: **Not Approved**

COGCC Representative: Any response to corrective action needs to satisfy COGCC rules. If corrective action is not addressed it could result in enforcement actions.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: _____

Title: Operation/Regulatory Tech

Date: 8/10/2018 2:33:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401730806	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files