

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401945124

Date Received:

02/20/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 51065

Name of Operator: LOEB LLC\* HERMAN L

Address: P O BOX 838

City: LAWRENCEVILLE State: IL Zip: 62439

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Middagh, Jesse	815-556-0756	jesse@loeboil.com
Pelton, Shane	620-617-5870	shane@loeboil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682600610

Inspection Date: 01/31/2019

FIR Submit Date: 02/01/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOEB LLC\* HERMAN L

Company Number: 51065

Address: P O BOX 838

City: LAWRENCEVILLE State: IL Zip: 62439

LOCATION - Location ID: 321668

Location Name: WHITE 'AL'-614S42W Number: 24NWSE County: CHEYENNE

Qtrqtr: NWSE Sec: 24 Twp: 14S Range: 42W Meridian: 6

Latitude: 38.818244 Longitude: -102.059852

FACILITY - API Number: 05-017-00 Facility ID: 207725

Facility Name: WHITE 'AL' Number: 1

Qtrqtr: NWSE Sec: 24 Twp: 14S Range: 42W Meridian: 6

Latitude: 38.818244 Longitude: -102.059852

CORRECTIVE ACTIONS:

1 CA# 122240

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 03/02/2019

Response: CA COMPLETED

Date of Completion: 02/19/2019

Operator Comment: Not Yet Corrected, Plan is in place pending adequate weather conditions. Hard cake build up around well head cannot be safely and properly removed until after ground thaws. Plan is to digout during upcoming spring season and replace with fresh soil / sand. Seeking extension of deadline to execute actual field corrective actions.

COGCC Decision: Not Approved

COGCC Representative: Operator is making request to change Corrective Action date after Field Inspection Report has already been issued.

2  CA# 122241

Corrective Action: Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.

Date: 02/02/2019

Response: CA COMPLETED

Date of Completion: 02/02/2019

Operator Comment: Casing vent was removed from wellhead. Valve closed and plug installed. Photo attached. Operator is taking necessary steps including data collection to seek request for venting from COGCC in near future.

COGCC Decision: Approved

COGCC Representative:

3  CA# 122242

Corrective Action: Install sign to comply with Rule 210.b.

Date: 03/02/2019

Response: CA COMPLETED

Date of Completion: 02/04/2019

Operator Comment: Updated contact information on signage. Photo attached.

COGCC Decision: Approved

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Two corrective actions implemented. Third corrective action is planned pending ground/weather conditions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jesse Middagh

Signed: \_\_\_\_\_

Title: Manager; E&P Ops

Date: 2/20/2019 10:03:36 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401945124	FIR RESOLUTION SUBMITTED
401945202	Contact Info Updated on well signage
401945203	Well vent removed, closed valve, plugged

Total Attach: 3 Files