

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401945322  
Date Received:  
02/20/2019

FIR RESOLUTION FORM

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 51065  
Name of Operator: LOEB LLC\* HERMAN L  
Address: P O BOX 838  
City: LAWRENCEVILLE State: IL Zip: 62439  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Middagh, Jesse	815-556-0756	jesse@loeboil.com
Pelton, Shane	620-617-5870	shane@loeboil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682600608  
Inspection Date: 01/31/2019 FIR Submit Date: 02/01/2019 FIR Status:

Inspected Operator Information:

Company Name: LOEB LLC\* HERMAN L Company Number: 51065  
Address: P O BOX 838  
City: LAWRENCEVILLE State: IL Zip: 62439

LOCATION - Location ID: 321694

Location Name: WHITE AL-614S42W Number: 24NESE County: CHEYENNE  
Qtrqtr: NESE Sec: 24 Twp: 14S Range: 42W Meridian: 6  
Latitude: 38.818954 Longitude: -102.055057

FACILITY - API Number: 05-017-00 Facility ID: 207803

Facility Name: WHITE AL Number: 2  
Qtrqtr: NESE Sec: 24 Twp: 14S Range: 42W Meridian: 6  
Latitude: 38.818954 Longitude: -102.055057

CORRECTIVE ACTIONS:

1 CA# 122237

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e. Date: 03/02/2019

Response: CA COMPLETED Date of Completion: 02/19/2019

Operator Comment: Partially completed. Plan is in place pending adequate weather and ground conditions to fully complete job. Hard cake buildup around well head cannot be safely and properly removed until ground conditions improve. Plan is to digout wellhead during upcoming spring season and replace with fresh soil / sand. Seeking extension of deadline to execute final stage of field corrective actions.

COGCC Decision: **Not Approved**

COGCC Representative: Operator is making request for extension of Corrective Action deadline after report has been publicly issued.

2  CA# 122238

Corrective Action: Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details. Date: 02/02/2019

Response: CA COMPLETED Date of Completion: 02/02/2019

Operator Comment: Casing vent was removed from wellhead. Valve closed and plug installed. Photo attached. Operator is taking necessary steps including data collection to seek request for venting from COGCC in near future.

COGCC Decision: Approved

COGCC Representative:

3  CA# 122239

Corrective Action: Install sign to comply with Rule 210.b. Date: 03/02/2019

Response: CA COMPLETED Date of Completion: 02/04/2019

Operator Comment: Updated contact information on signage. Photo attached.

COGCC Decision: Approved

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective action implemented. Hard cake around well head will be fully dug out in spring and replaced with fresh soil / sand.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jesse Middagh Signed: \_\_\_\_\_

Title: Manager; E&P Ops Date: 2/20/2019 10:56:53 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
401945322	FIR RESOLUTION SUBMITTED
401945348	Contact information updated on well signage
401945351	Valve closed and plug installed on casing vent

Total Attach: 3 Files