

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401952598
Date Received:
02/26/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

Abby Bazin

720-587-2356

abby.bazin@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504514

Inspection Date: 02/20/2019

FIR Submit Date: 02/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 460414

Location Name: LD07-01 MULTI Number: _____ County: _____

Qtrqtr: NENE Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772200 Longitude: -103.901750

FACILITY - API Number: 05-123-00 Facility ID: 460414

Facility Name: LD07-01 MULTI Number: _____

Qtrqtr: NENE Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772200 Longitude: -103.901750

CORRECTIVE ACTIONS:

1 CA# 122616

Corrective Action: Install required stormwater and erosion control BMPs in accordance with Rule 1002.f and stabilize soil stockpiles in accordance with 1002.c

Date: 02/27/2019

Response: CA COMPLETED

Date of Completion: 02/26/2019

Operator Comment: Filtrex has been repaired to maintain contact with the soil surface. Topsoil piles were actively being constructed during the inspector's visit. Topsoil piles were tracked to minimize wind erosion that same afternoon. A water truck will also be used at this location to mitigate windblown dust.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 122617

Corrective Action: Comply with rule 1002.e and 1002.f, and immediately install required stormwater and erosion control BMPs to stabilize the location and mitigate wind erosion and sediment transport.

Date: 02/20/2019

Response: CA COMPLETED

Date of Completion: 02/26/2019

Operator Comment: BMPs have been repaired so that they are properly installed. Stockpiles have been tracked and a water truck is being used to mitigate wind erosion. Surface disturbance is currently limited to the production facility pad. Construction of the well pad within the same disturbance footprint has not started.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 2/26/2019 5:18:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files