

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401903555  
Date Received:  
01/14/2019

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10454  
Name of Operator: PETROSHARE CORPORATION  
Address: 9635 MAROON CIRCLE #400  
City: ENGLEWOOD State: CO Zip: 80112  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Thorlaksen, Greg	(719) 963-0714	gregthorlaksen@yahoo.com
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com
Pesicka, Conor		conor.pesicka@state.co.us
Gomez, Jason		jason.gomez@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688400987  
Inspection Date: 01/07/2019 FIR Submit Date: 01/07/2019 FIR Status:

Inspected Operator Information:

Company Name: PETROSHARE CORPORATION Company Number: 10454  
Address: 9635 MAROON CIRCLE #400  
City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 320190

Location Name: (UPRR) KALCEVIC-62S63W Number: 3SENW County: ADAMS  
Qtrqtr: SENW Sec: 3 Twp: 2S Range: 63W Meridian: 6  
Latitude: 39.906780 Longitude: -104.425600

FACILITY - API Number: 05-001-00 Facility ID: 202957

Facility Name: (UPRR) KALCEVIC Number: 22-3  
Qtrqtr: SENW Sec: 3 Twp: 2S Range: 63W Meridian: 6  
Latitude: 39.906780 Longitude: -104.425600

CORRECTIVE ACTIONS:

1 ☒ CA# 121541

Corrective Action: Comply with rule 1103 Date: 02/07/2019  
Response: CA COMPLETED Date of Completion: 01/08/2019

Lines were cut and capped underground.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 121542

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/08/2019

Response: CA COMPLETED

Date of Completion: 01/08/2019

Operator  
Comment:

Leaking valve was repaired, as was load pot. Contaminated soil was hauled to disposal in a tote.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 121543

Corrective Action: Install wildlife screen per Rule 605.b.(7).

Date: 02/07/2019

Response: CA COMPLETED

Date of Completion: 01/08/2019

Operator  
Comment:

Screen was installed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

4 ☒ CA# 121544

Corrective Action: Install sign to comply with Rule 210.e.

Date: 02/07/2019

Response: CA COMPLETED

Date of Completion: 01/09/2019

Operator  
Comment:

New signs were installed.

COGCC Decision: Approved

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Devin Brown

Signed: \_\_\_\_\_

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401903555	FIR RESOLUTION SUBMITTED
401903566	Load valve repaired
401903567	New NFPA sticker applied
401903568	Stained soil removed and backfilled

Total Attach: 4 Files