


FORM 6 Rev 05/18	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				DE	ET	OE	ES
	WELL ABANDONMENT REPORT				Replug By Other Operator			
	This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.				Document Number: <div style="text-align: center;">401954743</div> Date Received:			
OGCC Operator Number: <u>5</u>					Contact Name: <u>Dave Andrews</u>			
Name of Operator: <u>COLORADO OIL & GAS CONSERVATION</u>					Phone: <u>(303) 894-2100x5686</u>			
Address: <u>1120 LINCOLN ST SUITE 801</u>					Fax: _____			
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>					Email: <u>david.andrews@state.co.us</u>			
For "Intent" 24 hour notice required,					Name: <u>Wentzel, Dougo</u> Tel: <u>(970) 986-7314</u>			
COGCC contact:					Email: <u>dougo.wentzel@state.co.us</u>			
API Number <u>05-077-05148-00</u>					Well Number: <u>1</u>			
Well Name: <u>GOVT-BAKER</u>					Location: QtrQtr: <u>SESW</u> Section: <u>21</u> Township: <u>8S</u> Range: <u>97W</u> Meridian: <u>6</u>			
County: <u>MESA</u>					Federal, Indian or State Lease Number: _____			
Field Name: <u>DE BEQUE</u>					Field Number: <u>16150</u>			
<input checked="" type="checkbox"/> Notice of Intent to Abandon					<input type="checkbox"/> Subsequent Report of Abandonment			
<i>Only Complete the Following Background Information for Intent to Abandon</i>								
Latitude: <u>39.340167</u>			Longitude: <u>-108.226750</u>					
GPS Data:								
Date of Measurement: _____			PDOP Reading: _____			GPS Instrument Operator's Name: _____		
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems								
<input checked="" type="checkbox"/> Other <u>Orphan Well Program Plugging</u>								
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			Estimated Depth: <u>254</u>					
Fish in Hole: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			If yes, explain details below					
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input type="checkbox"/> No			If yes, explain details below					
Details: <u>Fish consisting of wood and rock debris approximatley 3'-4' from surface. Pond is present at the surface.</u>								
Current and Previously Abandoned Zones								
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth			
MESAVERDE	251	254	11/11/1957	CEMENT	100			
Total: 1 zone(s)								
Casing History								
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
OPEN HOLE	13			254	0	0	0	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 65 sks cmt from 251 ft. to 170 ft. Plug Type: OPEN HOLE Plug Tagged: ☒

Set 65 sks cmt from 150 ft. to 69 ft. Plug Type: OPEN HOLE Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 65 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Plugging Date: _____
of _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

This well to be plugged as part of the Orphan Well Program by the COGCC.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Dave Andrews

Title: OWP Manager Date: 2/28/2019 Email: david.andrews@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: _____

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

401954779	WELBORE DIAGRAM
-----------	-----------------

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)