

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	OTHER		
Comment:	IMPACKED SOIL UNDER DRIVEHEAD MOTOR. REMOVE INPACKED SOIL AND FIX MECHANICAL ISSUE RESULTING IN SOIL CONTAMINATION.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	03/28/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 260246 Type: WELL API Number: 071-07412 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP INSPECTION TO INSP DOC#688401080 IN RESPONCE TO FIRR DOC#401913529. ALL CORRECTIVE ACTION HAVE BEEN COMPLETED HOWEVER THERE IS A NEW CORRECTIVE ACTION UNDER HOUSEKEEPING.	beardsit	02/28/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100247	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4748443