


Inspection Photo (s)
Hilton KP 312-25
API # 05-045-18451
FIR Inspection # 689303448



Location Photo #1



Location Photo #2



Inspection Photo (s)
Hilton KP 312-25
API # 05-045-18451
FIR Inspection # 689303448



Location Photo #3



**Location Photo #4, Unused/unmarked
flowline riser, near separators.**

Inspection Photo (s)
Hilton KP 312-25
API # 05-045-18451
FIR Inspection # 689303448



Location Photo #5, Missing BBL quantity on 4 production tanks.



Location Photo #6, Missing BBL quantity on 4 production tanks.