

**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #3**



**Location Photo #4**

**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #5, Missing tank information on fuel barrel.**



**Location Photo #6, Missing tank information on fuel barrel.**



**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #7, condensate in secondary drip pan.**



**Location Photo #8, unused/unmarked flow line riser by tank battery.**

**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #9, Leaking line.**



**Location Photo #10, area near the leaking line.**



**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #11, Area of the leak.**



**Location Photo #12, Area of the leak.**

**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #13, Area of the leak.**



**Location Photo #14, Area of the leak.**



**Inspection Photo (s)**  
**Hilton 23-1**  
**API # 05-045-16111**  
**FIR Inspection # 689303450**



**Location Photo #15, Location of the leak.**