

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2019

Submitted Date:

03/11/2019

Document Number:

688401435**FIELD INSPECTION FORM**Loc ID 452914 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458712	WELL	DG	11/26/2018		001-10262	B-Farm LD 18-389HN	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 458712 Type: WELL API Number: 001-10262 Status: DG Insp. Status: DG

**Complaint**

Comment: Inspection in response to complaint

Field Inspector Assigned: Randy Silver

Complaint Received:

Date 3-11-2019

Location# 452914

Inspection Document # 200447051

Nature of complaint odor

Field Inspector Actions:

On 3-11-2019, I was contact by supervisor Jason Gomez in reference to a complaint received by the COGCC in reference to odor. The Complainant stated the issues were coming from drilling rigs on the north and south side of HWY 7 and Holly street. I identified one rig on the south side of HWY 7 near Holly street. Precision rig 466 a Great western well site.

Complaint: Air Quality/odor and lighting

On 3-11-2019, I drove to complainant's house and did not smell any unusual odor's around complainant's residents. At approximately 1630 hrs I contacted complainant he informed me there is a strong diesel or petroleum sell around his residents in the AM hrs. He also had concerns with lighting from rig shinning toward his residents. I performed an onsite inspection of rig in question on location BFarm LD 18-389HN on 3-11-2019. At time of inspection I walked around all 4 sides of location and did not smell any strong or unusual odors. At time of inspection all lighting inside sound walls appeared to be pointing down toward the center of location.

At time of inspection no violation's per COGCC rules were found see inspection DOC# 688401433.

All information reviewed and site inspection were submitted to the COGCC for further review.

Corrective Action:

Date: