


<b>FORM</b> <b>6</b> Rev 05/18	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				DE ET OE ES
	<b>WELL ABANDONMENT REPORT</b>				<b style="color: red;">Replug By Other Operator</b>  Document Number: <div style="text-align: center;">401773610</div>  Date Received: <div style="text-align: center;">10/01/2018</div>
	<small>           This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.            A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.         </small>				

OGCC Operator Number: <u>8960</u>	Contact Name: <u>Kate Miller</u>
Name of Operator: <u>BONANZA CREEK ENERGY OPERATING COMPANY</u>	Phone: <u>(720) 440-6133</u>
Address: <u>410 17TH STREET SUITE #1400</u>	Fax: _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: <u>kmiller@bonanzacrk.com</u>
For "Intent" 24 hour notice required, Name: _____ Tel: _____ COGCC contact: Email: _____	

API Number <u>05-123-07388-00</u>	Well Name: <u>BOHLMAYER</u>	Well Number: <u>1</u>	
Location: QtrQtr: <u>NWSW</u> Section: <u>6</u> Township: <u>5N</u> Range: <u>61W</u> Meridian: <u>6</u>			
County: <u>WELD</u>	Federal, Indian or State Lease Number: _____		
Field Name: <u>WILDCAT</u>	Field Number: <u>99999</u>		

☐ Notice of Intent to Abandon
 ☒ Subsequent Report of Abandonment

<i>Only Complete the Following Background Information for Intent to Abandon</i>	
Latitude: <u>40.428960</u>	Longitude: <u>-104.259850</u>
GPS Data:	
Date of Measurement: <u>04/06/2015</u>	PDOP Reading: <u>1.9</u>
GPS Instrument Operator's Name: _____ Lat <u>40</u>	
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems <input type="checkbox"/> Other _____	
Casing to be pulled: <input type="checkbox"/> Yes <input type="checkbox"/> No	Estimated Depth: _____
Fish in Hole: <input type="checkbox"/> Yes <input type="checkbox"/> No	If yes, explain details below
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input type="checkbox"/> No	If yes, explain details below
Details: _____	

Current and Previously Abandoned Zones					
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
Total: 0 zone(s)					

Casing History								
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	72	70	72	0	VISU
OPEN HOLE	7+7/8			6,897				

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 450 sks cmt from 3787 ft. to 2931 ft. Plug Type: OPEN HOLE Plug Tagged: ☒

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 390 sacks half in. half out surface casing from 1000 ft. to 0 ft. Plug Tagged: ☐

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. \_\_\_\_\_ inch casing Plugging Date: 08/30/2018  
of \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: Ranger Energy Services

Type of Cement and Additives Used: Class "G" Cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

Bohlmeier 1 was originally plugged and abandoned as a "dry hole" on 11/31/1971 by Davis Oil Company.

Bonanza is going back in to this well to re-plug and abandon due to offset well mitigation.

Original plugs drilled out to approximately 888'MD, cleaned out well to 3787'MD. Cemented from 3787'MD w/ 450 sxs cement, tagged cement at 2931'MD. Set plug at 1000'MD and cemented with 390 sxs cement to surface.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Ashley Noonan

Title: Sr. Regulatory Analyst Date: 10/1/2018 Email: anoonan@progressivepcs.net

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Strathman, Elliot Date: 3/14/2019

### CONDITIONS OF APPROVAL, IF ANY:

#### COA Type

#### Description

--	--

### Attachment Check List

Att Doc Num

Name

1801648	WELLBORE DIAGRAM
401773610	FORM 6 SUBSEQUENT SUBMITTED
401780729	CEMENT JOB SUMMARY
401780730	CEMENT JOB SUMMARY

Total Attach: 4 Files

### General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)