

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2019

Submitted Date:

03/14/2019

Document Number:

689100198**FIELD INSPECTION FORM**
 Loc ID 330378 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.inspections@crestonep r.com	ALL INSPECTIONS
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251192	WELL	TA	03/01/2015	OW	123-18995	RASMUSSEN 19-12	PA

General Comment:

Inspected FacilitiesFacility ID: 251192 Type: WELL API Number: 123-18995 Status: TA Insp. Status: PA**Complaint**

Comment: **COGCC Inspection Report Summary**
On 1/18/2019 at approximately 0800 hrs, I, Inspection Supervisor Jason E. Gomez, was contacted by COGCC complaint Specialist Megan Adamczyk in reference to a possible noise complaint in the area off county line road near the Crestone Rasmussen location near Longmont. I attempted to make phone contact with the complaint Rod Brueske, he had indicated in his complaint he was experiencing noise coming from the Extraction Rinn Valley location located NE of his home.
I went to the Rinn Valley on 1/18/2019 at approximately 0840 hrs to perform a site inspection. Upon arrival I conducted an on-site inspection at Extraction Rinn Valley Location, I observed a flow back operation which was in the process of being completed in the area in Weld County Colorado.
I spoke with Jeff Rickard of Extraction who indicated the operation was in the process of completion and there was no abnormal activity at the time of the noise complaint. No sound study was conducted at the time of the inspection due to high winds in the area at the time of the inspection.
This is a summary of inspection report at the time of the inspections no compliance issues were observed.

Corrective Action:

Date: