

Status	Receipt	Permit	TWN	tdir	RNG	rdir	SEC	Q160	Q40	UTM_x	UTM_y	Use	Contact/Sample Attempts	Full Name
Eliminated - Use	0220843F	26051-F	1 N		68 W		4 NE	NE		499913.1	4437417.5	Other (Monitoring)	-	RKY MTN ENERGY
Eliminated - No Permit	6245		1 N		68 W		4 NE	SW		499492.9	4436864	Other	-	ROCKY MTN ENER
Eliminated - Use	0220843H	26049-F	1 N		68 W		4 NE	SW		499484.5	4436799.5	Other (Monitoring)	-	RKY MTN ENERGY
Eliminated - Use	0219942G	25574-F	1 N		68 W		4 NE	SW		499499.7	4436814.9	Other (Monitoring)	-	ROCKY MOUNTAIN ENERGY CO
Eliminated - Use	0220843I	26048-F	1 N		68 W		4 SE	NW		499483	4436340.5	Other (Monitoring)	-	RKY MTN ENERGY
Eliminated - Use	0220843D	26053-F	1 N		68 W		4 SE	SE		499772.3	4436267.5	Other (Monitoring)	-	RKY MTN ENERGY
Eliminated - Use	0220843E	26052-F	1 N		68 W		4 SE	SE		499954.5	4436071	Other (Monitoring)	-	RKY MTN ENERGY
Eliminated - Use	0220843A	26059-F	1 N		68 W		4 SE	SW		499527.8	4436051.5	Other (Monitoring)	-	RKY MTN ENERGY
Eliminated - Use	0220843B	26058-F	1 N		68 W		4 SE	SW		499527.7	4436036.5	Other (Monitoring)	-	RKY MTN ENERGY
Eliminated - Previous Sample	260350	142368-	1 N		68 W		3 NW	SE		500551.9	4437028.5	Domestic	Facility ID 754000, Sample date 2/11/15	NAAB, J
Eliminated - Use	58936	58936-MH	1 N		68 W		3 SW	SW		500126	4435962	Monitoring/Sampling	-	TERRACON CONSULTANTS INC
Eliminated - Not functional	9062771	20426-R	1 N		68 W		3 SE	SW		500893.8	4436676.5	Irrigation	Spoke with landowner 1/25/19. Well is not functional and hasn't been used in 25+ years	RIEDER HOME PLACE
Eliminated - No well	C620737	737-WCB	1 N		68 W		3 SE	SW		501098.9	4436062.5	Irrigation, Stock	Spoke with landowner 1/25/19. Only has one well.	RIEDER HOME PLACE
Eliminated - Use	23691	23691-MH	1 N		68 W		3 NE			501297.9	4437084.4	Monitoring/Sampling	-	CO DEPT TRANSPORTATION
Eliminated - No Well	C620704	704-WCB	1 N		68 W		3 NE	NE		501498.8	4437289.5	Irrigation	Not able to identify a landowner in the past, however sent letter to WTF LLC 2/25/19 in case well might be on their land. Received call from an agent for WTF LLC, well does not exist.	WTF LLC
Eliminated - Use	34738	34738-MH	1 N		68 W		3 NE	NW		501097.7	4437286.4	Monitoring/Sampling	-	GOODSON & ASSOC
Eliminated - Use	58100	58100-MH	1 N		68 W		3 NE	SE		501553.5	4436952.8	Monitoring/Sampling	-	4RIVERS PROPERTIES LLC
Eliminated - Use	58100	58100-MH	1 N		68 W		3 NE	SE		501553.5	4436952.8	Monitoring/Sampling	-	TERRACON CONSULTANTS INC
Eliminated - No well	9064917	60050	1 N		68 W		9 NE	NE		499280	4435047.5	Domestic, Stock	Landowner said they have no wells on the property.	HOGAN, RAYMOND
Permit Expired	913308	94887	1 N		68 W		9 NE	NE		499768.1	4435514.5	Domestic	-	HODD, KENNETH J
Permit Expired	912703	89430	1 N		68 W		9 NE	NW		499637.1	4435473.5	Domestic	-	VALDEZ, JOHN A
Eliminated - No well	9064535	47138	1 N		68 W		9 NE	NW		499280	4435047.5	Domestic	Landowner said they have no wells on the property.	MULLEN, WILLIAM
Permit Canceled	903526	41605	1 N		68 W		9 NE	NW		499280	4435047.5	Domestic	-	PROPP, JOHN
Permit Expired	903130	37555	1 N		68 W		9 NE	SE		499854.5	4434256.5	Domestic	-	GREEN, EARL L
Eliminated - Use	39154	39154-MH	1 N		68 W		9 NE	SW		499485	4435244.9	Monitoring/Sampling	-	PROPP, DARRYL
Permit Expired	910940	77190	1 N		68 W		9 NE	SW		499390.3	4435303.4	Domestic	-	PROPP, DARYLL
Permit Expired	343209	81991--A	1 N		68 W		9 NE	SW		499557.9	4435336.9	Domestic	-	PEACH, CHRISTOPHER S
Eliminated - No access	9065650	81991	1 N		68 W		9 NE	SW		499557.9	4435336.9	Domestic	According to landowner well is not used and does not have a pump installed.	NELSON BARARA JEAN
Permit Expired	7277	81991--A	1 N		68 W		9 NE	SW		499557.9	4435336.9	Domestic	-	HENRY, JOHN H
Eliminated - No Contact	9065228	70451	1 N		68 W		9 NE	SW		499549.2	4435200	Domestic	Sent access letters 9/19/17, 11/7/18, 2/6/19, no response. Visited site Nov 2017, did not see a residence or anyone to speak with.	MIRAMONTES, CARLOS
Eliminated - Use	58938	58938-MH	1 N		68 W		10 NW	NW		500103.1	4435848.4	Monitoring/Sampling	-	TERRACON CONSULTANTS INC