

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2019

Submitted Date:

03/18/2019

Document Number:

697300014**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		cogccinspection@pdce.com	
Liesenfeld, Zack		Zack.Liesenfeld@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458525	SPILL OR RELEASE	CL	11/21/2018		-	Ludwig 3	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.
Photos attached to document site condition at the time of inspection.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Location**Lease Road:**

Type	Access		
comment:	Access road changing. Existing road in process of reclamation.		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Sign indicating spreadfield closed present.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Land Application	Adequate		
Comment	Spreadfield BMP's are in place. West Field was deep ripped. Salt crust still present throughout (see photos).			
Corrective Action				Date:

Spill/Remediation:

Comment:				
Corrective Action:				Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

COGCC Comments

Comment	User	Date
The inactive spreadfield is in the process of final incorporation prior to sampling for regulatory closure. BMP's are in place. Pipeline disturbance is ongoing to the south of the facility. Area has been staked for future development of an oil and gas facility which will begin post regulatory closure.	graberc	03/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697300015	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766110
697300016	Salt crust on disturbed soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766111