

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2019

Submitted Date:

03/21/2019

Document Number:

693900096

FIELD INSPECTION FORM

Loc ID 326125 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215912	WELL	PR	09/04/1994	GW	067-07517	TUBBS 32-6-9 A 1	RI

General Comment:

[This is an interim reclamation and stormwater inspection.](#)

Inspected Facilities

Facility ID: 215912 Type: WELL API Number: 067-07517 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by irrigated grass fields, pinyon juniper woodland, and riparian vegetation associated with an adjacent stream. Revegetation is progressing within portions of the reclamation area, although sparse and eroding within the western project area.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action Date _____

1003a. Waste and Debris removed? Pass

Comment

Corrective Action Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action Date _____

Guy line anchors marked? _____

Comment

Corrective Action Date _____

1003b. Area no longer in use? In Production areas stabilized ?
 1003c. Compacted areas have been cross ripped?
 1003d. Drilling pit closed? Subsidence over on drill pit?
 Cuttings management:
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?
 Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA%
 TRANSECT RESULTS OF REFERENCE AREA%
 TOTAL % OF DESIRABLE VEGETATION COVER
 VEGETATIVE COVER

1003 f. Weeds Noxious weeds?

Comment

Corrective Action

Date

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA%
 TRANSECT RESULTS OF REFERENCE AREA%
 TOTAL % OF DESIRABLE VEGETATION COVER
 VEGETATIVE COVER

Comment:

Corrective Action:

Date

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Headcut erosion is occurring within the northern project area, resulting in erosional channeling. Additional erosion is occurring adjacent to facilities in the southwestern project area. See attached photos.

Corrective Action: Install stormwater controls to stabilize headcuts and other erosion within the project area.

Date: 04/30/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401981325	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4770560
401983425	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4772375
693900097	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4770558