

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2019

Submitted Date:

03/28/2019

Document Number:

693700154**FIELD INSPECTION FORM**Loc ID 424744 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10503Name of Operator: RED HAWK PETROLEUM LLCAddress: 1250 WOOD BRANCH PARK STE 400City: HOUSTON State: TX Zip: 77079**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Teresa Jackson		tjackson@atex-energy.com	Red Hawk Regulatory
Kevin Goebel		kgoebel@pedevco.com	Red Hawk Operations Manager
Axelson, John		john.axelson@state.co.us	COGCC Environmental Supervisor
Kraich, Adam		adam.kraich@state.co.us	COGCC Field Inspection Supervisor
Deanne Shepard		dshepard@pedevco.com	Red Hawk Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424741	WELL	PR	02/01/2018	OW	123-34161	Staudinger 1-31H	EI

General Comment:

This is a COGCC Environmental Staff inspection pertaining to the spill related to a fire at the heater treater. The lack of corrective actions related to damaged equipment does not indicate compliance with COGCC Rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	tubing placed adjacent pumpjack		
Corrective Action:	Comply with Rule 603.f. Corrective action date predated from previous inspection.	Date:	05/06/2018

Overall Good: ☐

Spills:					
Type	Area	Volume			
Crude Oil	WELLHEAD	<= 1 bbl			
Comment:	cruded oil leaking from wellhead				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Cleanup impacted material around wellhead and handle in accordance with Rule 907.e.				Date: 04/27/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	424741	Type:	WELL	API Number:	123-34161	Status:	PR	Insp. Status:	EI

--

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment:	Approximatley 40 yards of impacted material is stockpiled for disposal. Handle Impacted material in accordance with Rule 907.e. Provide disposal documentation (waste manifests) on Form 19 Supplemental Report.			
Corrective Action				Date:

Spill/Remediation:

Comment:	COGCC inspection of spill related to fire that occurred 3/6/2019 and reported to COGCC via Form 19 on 3/26/19. Notification of fire and spill was required by 3/7/2019, Form 19 Initial Spill Report was due 3/9/2019 and Form 19 Supplemental Spill Report was due 3/16/2019. Form 22 Accident Report was due 3/9/2019.			
Corrective Action:	Submit Form 19 and Form 22 as required by Rules 906 and 602, respectively. On a followup Form 19, submit root cause and corrective action for spill (cause of fire and prevention of future fire). Submit a site map showing area impacted by spill and include confirmation soil sample locations. Confirmation soil samples shall be collected from around the heater treater and from within the treater building at a minimum. Analyze soil samples for TPH-GRO, DRO, ORO and BTEX.			Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
693700157	Staudinger1-31H Photos 3-27-2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4776655