

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401988754

Date Received:

03/28/2019

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 76840

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Kevin Bothwell

Phone

970-534-0654

Email

kbothwell@schneideroilandgas.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682404240

Inspection Date: 11/28/2018

FIR Submit Date: 12/04/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC

Company Number: 76840

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

### LOCATION - Location ID: 320521

Location Name: RUBY Number: 1 County: \_\_\_\_\_

Qtrqr: SWSE Sec: 12 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.973650 Longitude: -104.946970

### FACILITY - API Number: 05-001-00 Facility ID: 320521

Facility Name: RUBY Number: 1

Qtrqr: SWSE Sec: 12 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.973650 Longitude: -104.946970

### CORRECTIVE ACTIONS:

1 ☒ CA# 120761

Corrective Action: Comply with Rule 1003. Corrective action date is being back dated to when interim reclamation should have been performed.

Date: 03/28/2018

Response: CA COMPLETED

Date of Completion: 03/27/2019

Operator  
Comment:

Interim reclamation has been completed and location has recently been re-seeded.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

Note: Based on the attached photos, it appears interim reclamation has been performed on all areas not needed for production operations.

2 ☒ CA# 120762

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 01/01/2019

Response: CA COMPLETED

Date of Completion: 03/27/2019

Operator Comment: Interim reclamation has been completed and has recently been re-seeded.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

Note: Based on the attached photos, it appears interim reclamation has been performed which includes the implementation of erosion control BMPs (e.g., straw crimped mulch and seeded).

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Interim reclamation and re-seeding has been completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kevin Bothwell

Signed: \_\_\_\_\_

Title: Employee

Date: 3/28/2019 4:31:54 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401988754	FIR RESOLUTION SUBMITTED
401988761	Ruby Reclam 1
401988763	Ruby Reclam 2
401988764	Ruby Reclam 3
401988766	Ruby Reclam 4

Total Attach: 5 Files