

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2019

Submitted Date:

03/29/2019

Document Number:

689900518**FIELD INSPECTION FORM**
 Loc ID 320971 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10237Name of Operator: JONES ENERGY LTDAddress: 807 LAS CIMAS PKWY #350City: AUSTIN State: TX Zip: 78746**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MEYER, BOB		bmeyer@jonesenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205603	WELL	PA	02/29/1968	DSPW	009-06014	ROLLINS-RUTHERFORD E 1-5-WD	RI

General Comment:

Reclamation Inspection.

This is a Follow Up of the previous inspections document #673502014, 673503262.

It does not appear that any reclamation corrective actions have been performed.

Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.(1). Perform corrective actions immediately to avoid further enforcement and potential penalties.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: It does not appear that the corrective actions from the previous inspections (document number 673502014, 673503262) have been performed. The corrective actions need to be performed as soon as possible to bring the location into compliance.

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Pass

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Pass

Compaction alleviation Fail Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Fail Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: The location is bare of vegetation growth approx. 120'x120'. The access road does not have adequate vegetation and contains undesirable weeds (kochia). SEE ATTACHED PHOTOS

Corrective Action: _____ Date **04/30/2015**

Remove and control weeds (debris) and Reseed the location and access road. Stabilize seeded soils (e.g. mulch).
Comply with 1004 Rules

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**COGCC Comments**

Comment	User	Date
Establish vegetation with total perennial non-invasive plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture that matches the adjacent pastureland or a seed mixture requested by the landowner. Continue to monitor and manage this site until Final Reclamation has Passed.	CostaR	03/29/2019
It appears the surrounding field is CRP vegetation. It is recommended that the soil at the location be sampled and analyzed to determine if soil issues exist. The soils seem to be compacted at the location which could be the reason that no vegetation grows.	CostaR	03/29/2019
Perform reseeding and all reclamation practices as soon as possible to facilitate the establishment of desirable vegetation within this spring growing season in order to comply with the 1004 reclamation requirements. The undesirable vegetative debris will need to be removed to allow for proper reseeding. The soils need to be decompacted to a depth of 18 inches and tilled to establish a proper seedbed. Once the disturbed areas have been reseeded a certified weed free mulch or equivalent soil stabilization method should be applied to the exposed soils. Weeds should be controlled to facilitate the establishment of desirable vegetation.	CostaR	03/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900519	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778538