

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401989287

Date Received:

03/29/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10471

Name of Operator: ARP PRODUCTION COMPANY LLC

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Randy Madison

575-420-1120

rmadison@atlasenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900498

Inspection Date: 03/25/2019

FIR Submit Date: 03/28/2019

FIR Status: _____

Inspected Operator Information:

Company Name: ARP PRODUCTION COMPANY LLC

Company Number: 10471

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 309087

Location Name: VPR C-635S66W Number: 6SENW County: LAS ANIMAS

Qtrqr: SENW Sec: 6 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.030110 Longitude: -104.824730

FACILITY - API Number: 05-071-

-00

Facility ID: 287870

Facility Name: VPR C Number: 142

Qtrqr: SENW Sec: 6 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.030110 Longitude: -104.824730

CORRECTIVE ACTIONS:

1 ☒ CA# 123586

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 03/30/2019

Response: CA COMPLETED

Date of Completion: 03/29/2019

Operator
Comment:

The 2" hammer union that was leaking was replaced. The water dissipated into the ground and evaporated.

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 123587

Corrective Action: Comply with the 1003 interim reclamation rules. Reseed and stabilize the cut slope.

Date: 05/03/2019

Response: CA COMPLETED

Date of Completion: 03/29/2019

Operator
Comment: That area was reseeded last fall. It is just getting warm enough for vegetation to grow. We will continue to monitor the area. If it needs reseeded again after it warms up and is given time to grow we will do so.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 123588

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/03/2019

Response: CA COMPLETED

Date of Completion: 03/29/2019

Operator
Comment: Road will be bladed and woddles installed in the ditch to prevent erosion along side the road.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This is an on going project. We will continue to monitor the area and try to establish vegetation on the slope.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison

Signed: _____

Title: HSE Specialist

Date: 3/29/2019 9:59:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401989287	FIR RESOLUTION SUBMITTED
401989343	C-142 Picture of Repair
401989344	C-142

Total Attach: 3 Files