

**Laramie Energy LLC .**  
**Api # 05-077-09438**  
**Inspection # 675002118**



**Photo of location From NE corner of the location**

Laramie Energy LLC .  
Api # 05-077-09438  
Inspection # 675002118



Photo of wellhead.

Photo of tank battery

Laramie Energy LLC .  
Api # 05-077-09438  
Inspection # 675002118



Photo #5. Unused equipment stored inside of tank containment



Photo # 6. Hole in liner inside of tank containment.

Laramie Energy LLC .  
Api # 05-077-09438  
Inspection # 675002118



Photo #7. Tank containment liner in need of repair.



Photo #8. Nearest access not posted on tank battery sign, wellhead sign or tank

Laramie Energy LLC .  
Api # 05-077-09438  
Inspection # 675002118



**Photo #8. Erosion and sediment moving onto the South corner of location from South corner slope. Berm not holding. BMP not maintained**



**Photo #9. Close up from same view as photo #8. Erosion and sediment moving onto location from South corner slope. Berm is not holding. BMP not maintained**

Laramie Energy LLC .  
Api # 05-077-09438  
Inspection # 675002118



**Photo #10. Storm Water Erosion moving off location on SW side of location along the South side of the access road**

**Photo #11. Storm Water Erosion moving off location on SW side of location along North side of the access road**

Laramie Energy LLC .  
Api # 05-077-09438  
Inspection # 675002118



**Photo #12. On the SW side of location, Storm Water Erosion is moving along the North side of the access road into a BMP that needs maintenance**

**Photo #13. Storm Water Erosion is moving off location on SW side of location along the North side of the access road.**