

US ROCKIES REGION
Operation Summary Report

Well: **FIRESTONE V20-02**

Spud date: 6/22/2007

Project: COLORADO-WELD-NAD83-UTM13

Site: FIRESTONE V20-02

Rig name no.: SPN 710/710

Event: CONST- CAP WELL WORK

Start date: 3/7/2019

End date:

Active datum: RKB @4,972.99usft (above Mean Sea Level)

UWI:

Date	Time Start-End	Duration (hr)	Phase	Code	Sub Code	P/U	MD from (usft)	Operation
2/22/2019	12:00 - 13:00	1.00	LOCPRP	53	B	P		ANCHORS + STRING FENCE LOCATION FOR UPCOMING RIG OPS
3/7/2019	16:00 - 17:30	1.50	MIRU	30	A	P		MIRU SPN 710
	17:30 - 18:30	1.00	WO/REP	47	A	P		RU PUMP. WINTERIZE EQUIP
	18:30 - 19:00	0.50	WO/REP	30	G	P		CREW TRAVEL TO YARD
3/8/2019	7:00 - 8:00	1.00	WO/REP	30	G	P		CREW TRAVEL TO LOC. JSA MEETING
	8:00 - 8:30	0.50	WO/REP	30	M	P		START & WARMUP EQUIP
	8:30 - 9:30	1.00	WO/REP	30	D	P		CHECK PRESS. TP 500#. CP 500#. SP 0#. RU HOLESEEKERS TESTING. TEST BOP BLIND & PIPE RAMS ON STUMP TO SPECS. OK (3K WH).
	9:30 - 12:30	3.00	WO/REP	30	E	P		BD WELL TO WORK TANK. CONTROL W/100 BW-BIO.
	12:30 - 13:30	1.00	WO/REP	30	F	P		ND WH TREE. INSTALL ADAPTOR FLANGE. NUBOP.
	13:30 - 15:30	2.00	WO/REP	31	I	P		RU HOLESEEKERS EMI UNIT. EMI WHILE TOO H. TOTAL 257 JTS(7925.67) 2-3/8" 4.7# J55, XN NC. 29 YELLOW, 225 BLUE, 3 RED. BAD JTS 143, 256, 257. RD EMI UNIT.
	15:30 - 17:30	2.00	WO/REP	31	I	P		PU CSG SCRAPER. TIH W/ 254 JTS TO 7850'. LD 22 JTS. SWI
	17:30 - 18:00	0.50	WO/REP	30	I	P		DRAIN PUMP. WINTERIZE EQUIP
	18:00 - 18:30	0.50	WO/REP	30	G	P		CREW TRAVEL TO YARD
3/9/2019	6:00 - 7:00	1.00	WO/REP	30	G	P		CREW TRAVEL TO LOC. JSA MEETING
	7:00 - 7:30	0.50	WO/REP	30	M	P		START & WARMUP EQUIP
	7:30 - 9:00	1.50	WO/REP	31	I	P		PRESS. TP 0#. CP 0#. SP 0#. TOO H LD SCRAPER.
	9:00 - 11:00	2.00	WO/REP	31	G	P		TIH W/4.5" CTS 10K RBP, 232 JTS. SET @ 7170'. JAY OFF RBP LD 1 JT.
	11:00 - 12:00	1.00	WO/REP	31	H	P		CIRC GAS OUT
	12:00 - 12:30	0.50	WO/REP	52	G	P		PT CSG/RBP TO 1000# HOLD FOR 15 MIN TEST OK.
	12:30 - 13:00	0.50	WO/REP	31	H	P		PUMP 2 SX SAND CHASED W/10 BW.
	13:00 - 14:30	1.50	WO/REP	31	I	P		TOOH
	14:30 - 15:30	1.00	WO/REP	30	J	P		ND BOP. REMOVE 3K WH. INSTALLED 5K WH. NU BOP. SWI
	15:30 - 16:00	0.50	WO/REP	30	I	P		DRAIN PUMP. WINTERIZE EQUIP
	16:00 - 16:30	0.50	WO/REP	30	G	P		CREW TRAVEL TO YARD
3/11/2019	6:00 - 7:00	1.00	WO/REP	30	G	P		CREW TRAVEL TO LOC. JSA MEETING
	7:00 - 7:30	0.50	WO/REP	30	M	P		START & WARMUP EQUIP
	7:30 - 9:30	2.00	WO/REP	31	I	P		CHECK PRESS CP 0# SP 0#. PU 4.5" 10K CTS RBP TIH W/229 JTS
	9:30 - 10:30	1.00	WO/REP	31	H	P		SET RBP @ 7078' KB. JAY OFF RBP LD 2 JTS. DUMP 2 SX SAND CHASED W/10 BW. LAND W/227 JTS 2-3/8" 4.7# J55, XN, RETREAVING HEAD EOT @ 7023' KB.
	10:30 - 11:30	1.00	WO/REP	30	J	P		ND BOP. NUWH. RU HOLESEEKERS TESTING. TORQ & TEST WH TO 5K. TEST OK. RD TESTER.
	11:30 - 12:30	1.00	RDMO	30	C	P		RACK PUMP. RDMO TO MCPEEK 13-10A