

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2019

Submitted Date:

04/08/2019

Document Number:

693900144

FIELD INSPECTION FORM

Loc ID 306821 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268736	WELL	PR	07/21/2003	GW	067-08843	HJERMSTAD A 3	RI

General Comment:

[This is an interim reclamation and stormwater inspection.](#)

Inspected Facilities

Facility ID: 268736 Type: WELL API Number: 067-08843 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by sagebrush shrubland. Revegetation is progressing within the outer reclamation areas. Working area is fenced with portions of fenced area revegetating.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? _____

Comment Tall kochia debris observed within the reclamation areas.

Corrective Action Remove and properly dispose of kochia debris.

Date **05/10/2019**

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

1003b. Area no longer in use? In Production areas stabilized ?
 1003c. Compacted areas have been cross ripped?
 1003d. Drilling pit closed? Subsidence over on drill pit?
 Cuttings management:
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?
 Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA%
 TRANSECT RESULTS OF REFERENCE AREA%
 TOTAL % OF DESIRABLE VEGETATION COVER
 VEGETATIVE COVER

1003 f. Weeds Noxious weeds?

Comment

Corrective Action

Date

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA%
 TRANSECT RESULTS OF REFERENCE AREA%
 TOTAL % OF DESIRABLE VEGETATION COVER
 VEGETATIVE COVER

Comment:

Corrective Action:

Date

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The stream crossing over Salt Creek along the access road is eroding significantly and culverts are not sufficiently sized to convey major runoff events. See attached photos.

Corrective Action: Stabilize the Salt Creek stream crossing increase the conveyance capability so that it is capable of conveying flows during significant runoff events. Crossing should be constructed to ensure that culvert inlets and outlets are also stabilized.

Date: 05/03/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693900145	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788173