

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401993125
Date Received:
04/02/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Abby Bazin

720-587-2356

abby.bazin@nblenergy.com

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504592

Inspection Date: 03/08/2019

FIR Submit Date: 03/13/2019

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 460414

Location Name: LD07-01 MULTI Number: _____ County: _____

Qtrqtr: NENE Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772200 Longitude: -103.901750

FACILITY - API Number: 05-123- -00 Facility ID: 460414

Facility Name: LD07-01 MULTI Number: _____

Qtrqtr: NENE Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772200 Longitude: -103.901750

CORRECTIVE ACTIONS:

1 ☒ CA# 123208

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: _____

Response: CA COMPLETED

Date of Completion: 03/08/2019

Operator Comment: Ripping is repaired each day. Please see attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed, or that the COGCC is in agreement with operator comments within the attachment. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 123209

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: _____

Response: CA COMPLETED

Date of Completion: 03/18/2019

Operator Comment: Please see attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed, or that the COGCC is in agreement with operator comments within the attachment. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

Stormwater sediment and erosion control BMPs need to be site specific; if it is determined that a specific BMP is insufficient to mitigate degradation on a site, cannot be implemented per installation specification, or maintained in effective operating condition, then alternative BMPs that are better suited to meet the site's conditions should immediately be considered and applied, or used in conjunction.

3 ☒ CA# 123210

Corrective Action: Comply with rule 1002.e and 1002.f

Date: _____

Response: CA COMPLETED

Date of Completion: 03/18/2019

Operator Comment: Please see attached.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC decision "Not Approved". Corrective action without date entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 4/2/2019 12:05:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401993125	FIR RESOLUTION SUBMITTED
-----------	--------------------------

401993129	LD07-01 Pad Response Photo Log
-----------	--------------------------------

Total Attach: 2 Files