

W-6--4
Api. # 05-045-06506
Inspection # 689703008



W-6--4
Api. # 05-045-06506
Inspection # 689703008



Brush of location.

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Unmarked deadman

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Unmarked deadman

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Dead weed debris

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Dead weed debris

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Open hole at gate of well fence.

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Farm tap on well



W-6--4
Api. # 05-045-06506
Inspection # 689703008



Farm tap line and regulator from well. Unmarked unused riser under gas regulator.

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Unmarked unused riser under gas regulator.

W-6--4
Api. # 05-045-06506
Inspection # 689703008



Farm tap supply line and regulator.