

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

688401843**FIELD INSPECTION FORM**

Loc ID 308967 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285981	WELL	PR	05/09/2008	GW	071-08888	APACHE CANYON 19-16	PR

General Comment:

Location				
Lease Road:				
Type	Main			
comment:	Road is in need of maintenance			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Stained soil around HYD motor skid, and a pile next to meter house.			
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A			Date: 05/12/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Compressor	# 1			corrective date
Comment:	Liquid ring. Vacuum pump observed on well without COGCC approval.			
Corrective Action:	Provide COGCC with documentaton showing approval of use of vacuum pump per rule 331.			Date: 05/03/2019
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 285981 Type: WELL API Number: 071-08888 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday April 12, 2019 at approximately 1056 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site, AC# 19-16 at API# 05-071-08888 in Las Animas County Colorado.</p> <p>While there, I observed a producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil; Rule 907 A Corrective action date of 5-12-19 See photos 3,4,5</p> <p>Vacuum on location; Rule 331 Corrective action date of 5-3-19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/12/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401844	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794078