

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

688401857

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312064 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274677	WELL	PR	10/22/2004	GW	071-08248	HILL RANCH 33-4X	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type OTHER		
	Comment: Location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type			
	Comment: Release of fluids		
Corrective Action:	Recover free liquids and properly dispose in accordance with 907.c.	Date:	04/26/2019
Type	OTHER		
	Comment: Mechanical issue; Packing appears to be leaking		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	04/13/2019

Overall Good:

Spills:

Type	Area	Volume			
In Containment: No					
Comment: <input style="width: 100%;" type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					

Fencing/:

Type			
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 274677 Type: WELL API Number: 071-08248 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday April 12, 2019 at approximately 1309 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site, HR#33-4X at API# 05-071-08248 in Las Animas County Colorado. While there, I observed a producing well site During this inspection the following possible compliance issues were observed: Mechanical Issue; Rule 605 d Corrective action date of 4-13-19 See photo 3 Release of fluid; Rule 907 c Corrective action date of 4-26-19 see photo 3 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401858	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794085