

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

688401867**FIELD INSPECTION FORM**Loc ID 333914 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258768	WELL	PR	04/24/2001	GW	071-07153	HILL RANCH 05-01R	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	location		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:		
Type	OTHER	
Comment:	Stained soil around WH and HYD motor skid	
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date: 05/12/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type		
Comment:		
Corrective Action:		Date:

Equipment:			corrective date
Type: Other	#		
Comment:	Braden head appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 258768 Type: WELL API Number: 071-07153 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday April 12, 2019 at approximately 1508 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site, HR#33-06V and HR#05-01R at API# 05-071-07153 in Las Animas County Colorado.</p> <p>While there, I observed a producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil; Rule 907 A Corrective action date of 5-12-19 See photos 3,4</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/12/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401868	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794090