

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER
Comment:	<p>PHOTO 3: IMPACTED SOIL ALL AROUND COMPRESSOR SKID PHOTO 4: IMPACTED SOIL ON WEST SIDE OF COMPRESSOR PRIME MOVER SKID. PHOTO 5: IMPACTED SOIL ON NORTH SIDE OF COMPRESSOR PRIME MOVER SKID. PHOTO 6: IMPACTED SOIL ON SOUTH SIDE OF COMPRESSOR PRIME MOVER SKID. PHOTO 7: IMPACTED SOIL ON NORTH SIDE OF PUMPJACK HYDRAULIC MOTOR. PHOTO 8: APP. 2" OF STANDING WATER WITH OIL CONTAMINATION IN COMPRESSOR SKID IS WITHIN APP. 2" FROM RUNNING OVER</p>

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.

Date: 05/17/2019

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment # 1

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date:

corrective date

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 217581 Type: WELL API Number: 071-06360 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100529	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4799472