

HILL RANCH 33-04X API# 05-071-08248 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 12, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401857



PHOTO 1: REPLACED THE PACKING TO ELIMINATE THE WATER LEAK. PACKINGS WERE SECURELY FASTENED. ABSORBENT PADS WERE USED TO DRY THE SURFACE, THEN REMOVED FROM LOCATION.

HILL RANCH 33-04X API# 05-071-08248 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 18, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401857



PHOTO 2: THE ABSORBENT PADS WERE USED TO RECOVER WATER, THEN REMOVED FROM LOCATION.