

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

688401827

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
333596 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280920	WELL	PR	07/01/2011	GW	071-08599	GOLDEN EAGLE 20-4	PR

**General Comment:**

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	stained soil around HYD motor skid		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A		Date: <u>05/11/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PIT		
Comment:	Electric fence		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas powered HYD motor skid		
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:

Type: Other	#	
Comment:	Braden appears to be plumbed to surface	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	15bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No berm			
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 280920 Type: WELL API Number: 071-08599 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Thursday April 11, 2019 at approximately 1648 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site GE #20-4, at API # 05-071-08599 in Las Animas County Colorado.                      While there, I observed a production well site.                      During this inspection the following possible compliance issues were observed:                      Stained soil; Rule 907 A Corrective action date of 5-11-19 See photos 3,4                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	04/11/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402005791	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792668">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792668</a>
688401828	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792648">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792648</a>