

APACHE CANYON 35-05 API# 05-071-08542 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100457



PHOTO 1: THE IMPACTED SOIL NEXT TO THE SEPARATOR HOUSE HAS BEEN CLEANED UP.

APACHE CANYON 35-05 API# 05-071-08542 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100457




PHOTO 2: THE IMPACTED SOIL NEXT TO THE WELL HEAD WAS CLEANED UP. ALL VALVES AND FITTINGS WERE SECURELY FASTENED. THE HYDRAULIC HOSES WERE CLEANED UP AS WELL.

APACHE CANYON 35-05 API# 05-071-08542 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100457



PHOTO 3: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS CLEANED UP.

APACHE CANYON 35-05 API# 05-071-08542 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100457



PHOTO 4: THE PRODUCED WATER WAS SENT BACK TO SURFACE WATER DISCHARGE AND THE WATER THAT WAS IN THE PIT WAS REMOVED USING A WATER VAC TRUCK ON 04/10/19.