

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

688401851**FIELD INSPECTION FORM**Loc ID 309172 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	<a href="#">All Inspections</a>
Mack, Ronald		ronaldmack@tcenergy.us	<a href="#">All Inspections</a>
Beardslee, Tom		tom.beardslee@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289458	WELL	PR	09/04/2007	GW	071-09202	HILL RANCH 29-13	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Road in need of repair.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil around WH and HYD motor skid.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	05/12/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 289458 Type: WELL API Number: 071-09202 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday April 12, 2019 at approximately 1223 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site, HR#29-13 at API# 05-071-09202 in Las Animas County Colorado.</p> <p>While there, I observed a producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil; Rule 907 A Corrective action date of 5-12-19 See photos 3,4</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/12/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402007399	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794099">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794099</a>
688401852	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794082">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794082</a>