

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

688401867

FIELD INSPECTION FORM

Loc ID 333914 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258768	WELL	PR	04/24/2001	GW	071-07153	HILL RANCH 05-01R	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	OTHER				
Comment:	location				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:					
Corrective Action:				Date:	

Good Housekeeping:

Type	OTHER				
Comment:	Stained soil around WH and HYD motor skid				
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A			Date:	05/12/2019

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type					
Comment:					
Corrective Action:				Date:	

Equipment:

					corrective date
Type: Other	#				
Comment:	Braden head appears to be plumbed to surface				
Corrective Action:				Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 258768 Type: WELL API Number: 071-07153 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday April 12, 2019 at approximately 1508 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site, HR#33-06V and HR#05-01R at API# 05-071-07153 in Las Animas County Colorado. While there, I observed a producing well site During this inspection the following possible compliance issues were observed: Stained soil; Rule 907 A Corrective action date of 5-12-19 See photos 3,4 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402007404	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794103
688401868	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794090