

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402016273

Date Received:

04/22/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Santistevan, Vince

719-845-2102/719-680-9705

vincasantistevan@tcenergy.us

Mack, Ronald

ronaldmack@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401785

Inspection Date: 04/09/2019

FIR Submit Date: 04/09/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 309291

Location Name: GOLDEN EAGLE-633S67W Number: 30SENW County: LAS ANIMAS

Qtrqtr: NENW Sec: 30 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.146672 Longitude: -104.928421

FACILITY - API Number: 05-071- -00 Facility ID: 291279

Facility Name: GOLDEN EAGLE Number: 30-3

Qtrqtr: NENW Sec: 30 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.146672 Longitude: -104.928421

CORRECTIVE ACTIONS:

1 CA# 124038

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 04/30/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator
Comment:

A red post was installed to mark the Deadman anchor. See attached photo log for details.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 124039

Corrective Action: Comply with Rule 603.f .
For unused , unmarked flowline risers 24 hrs to lock out tag out.
30 days to remove riser.

Date: 04/10/2019

Response: CA COMPLETED

Date of Completion: 04/10/2019

Operator
Comment: All risers were marked and LOTO.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 124040

Corrective Action: Location is within a designated setback location, install fencing per Rule 604.c.(2)M.

Date: 05/09/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator
Comment: The fence surrounding the production pit was repaired.

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 124041

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/09/2019

Response: CA COMPLETED

Date of Completion: 04/19/2019

Operator
Comment: The erosion of the fill slope along the main access road was corrected. Rip-rap was placed in these areas for erosion control and to stabilize the soil.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/22/2019 12:07:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402016328	Photo Log
-----------	-----------

Total Attach: 1 Files