

GOLDEN EAGLE 30-03 API# 05-071-09347 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 19, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401785



PHOTO 1: THE EROSION OF THE FILL SLOPE ALONG THE MAIN LEASE ROAD TO LOCATION HAS BEEN ADDRESSED. RIP-RAP WAS PLACED ON THE FILL SLOPE FOR SOIL STABILIZATION.

GOLDEN EAGLE 30-03 API# 05-071-09347 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 19, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401785



PHOTO 2: THE EROSION OF THE FILL SLOPE ALONG THE MAIN LEASE ROAD TO LOCATION HAS BEEN ADDRESSED. RIP-RAP WAS PLACED ON THE FILL SLOPE FOR SOIL STABILIZATION.

GOLDEN EAGLE 30-03 API# 05-071-09347 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 19, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401785



PHOTO 3: THE SEDIMENT WAS REMOVED FROM THE CULVERT INLET TO ALLOW STORMWATER TO FLOW THROUGH CULVERT.

GOLDEN EAGLE 30-03 API# 05-071-09347 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 12, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401785



PHOTO 4: THE FENCE SURROUNDING THE PRODUCTION PIT HAS BEEN REPAIRED.

GOLDEN EAGLE 30-03 API# 05-071-09347 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 12, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401785



PHOTO 5: THE FENCE SURROUNDING THE PRODUCTION PIT HAS BEEN REPAIRED.

GOLDEN EAGLE 30-03 API# 05-071-09347 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 12, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401785



PHOTO 6: THE DEADMAN ANCHOR WAS MARKED WITH A RED POST.

GOLDEN EAGLE 30-03 API# 05-071-09347 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401785



PHOTO 6: THE FLOW LINE RISERS WERE LABELED AND LOTO.