

**W-6-4**  
**Api. # 05-045-06506**  
**Inspection # 689703065**



**Brush has been cleared from location.**

**W-6-4**  
**Api. # 05-045-06506**  
**Inspection # 689703065**



**Deadman marker reinstalled.**

**W-6-4**  
**Api. # 05-045-06506**  
**Inspection # 689703065**



**Brush has been cleared from location.**

**W-6-4**  
**Api. # 05-045-06506**  
**Inspection # 689703065**



**Farm tap and unused riser have been removed.**