

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402024570

Date Received:
04/29/2019

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Reddy

970-515-1292

luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902808

Inspection Date: 04/24/2019

FIR Submit Date: 04/26/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 463802

Location Name: BARCLAY FARMS Number: 37-28HZ County: _____
PAD

Qtrqtr: NENE Sec: 28 Twp: 3N Range: 66W Meridian: 6

Latitude: 40.202398 Longitude: -104.776379

FACILITY - API Number: 05-123-

-00

Facility ID: 463802

Facility Name: BARCLAY FARMS Number: 37-28HZ
PAD

Qtrqtr: NENE Sec: 28 Twp: 3N Range: 66W Meridian: 6

Latitude: 40.202398 Longitude: -104.776379

CORRECTIVE ACTIONS:

1 CA# 124624

Corrective Action: Install, repair, or replace required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 04/25/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BMP's have not been installed and completed because inspection was done two days after construction began. BMP's were in process of being installed during inspection and ditch and berms were in process of being cut and built during the inspection.

The corrective action date was set for 4/25 and the inspection was not submitted until 4/26. A corrective action date in the past is not attainable.
All required stormwater BMP's will be installed on location but it takes longer than two days.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: BMP's have not been installed and completed because inspection was done two days after construction began. BMP's were in process of being installed during inspection and ditch and berms were in process of being cut and built during the inspection.
The corrective action date was set for 4/25 and the inspection was not submitted until 4/26. A corrective action date in the past is not attainable.
All required stormwater BMP's will be installed on location but it takes longer than two days.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: _____

Title: Regulatory Specialist

Date: 4/29/2019 10:41:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files